

Reference	Concern	Location	Primary parish	Status	Update to Parish Councils Feb 2023
ITCP/2016/01	Safety of pavement	Jules House, Cold Overton Road	Oakham	No work required	
ITCP/2016/02	Speeding	South Luffenham entrance	South Luffenham	Completed	
ITCP/2016/03	Speeding	Springback Way, Uppingham	Uppingham	Completed	
ITCP/2016/04	Accident cluster site	A606/ Barnsdale Avenue junction	Whitwell	No work required	
ITCP/2016/05	Accident cluster site	B1081, Old Great North Road	Tickencote	Completed	
ITCP/2016/06	Accident cluster site	Whissendine Road	Ashwell	Completed	
ITCP/2016/07	Accident cluster site	Junction of Burley Road and Oakham Road	Langham	No work required	
ITCP/2016/08	Uneven pavement	High Street	Ketton	Completed	
ITCP/2016/09	HGVs turning	Mill Lane	Tinwell	Completed	
ITCP/2016/10	Speeding	Main Road	Braunston	Completed	
ITCP/2016/11	Speeding	Seaton Road	Barrowden	Completed	
ITCP/2016/12	Speeding	Knossington Road/Main Road	Braunston	Completed	
ITCP/2016/13	Speeding	A6121	South Luffenham	Completed	

ITCP/2016/14	Lack of pedestrian crossing	A6121	South Luffenham	No work required	
ITCP/2016/15	HGVs turning	Junction of A47 with Wireless Hill	South Luffenham	No work required	
ITCP/2016/16	Lack of pull in	Pinfold Lane	South Luffenham	Completed	
ITCP/2016/17	Speeding	Main Road	Barleythorpe	Completed	
ITCP/2016/17 - REV	Speeding	Main Road	Barleythorpe	No work required	
ITCP/2016/18	Safety concerns	Coach Road	Exton	No work required	
ITCP/2017/01	Lack of footpath	Main Road	Little Casterton	Closed - no work required.	This scheme was not progressed due to constraints within the adopted highway
ITCP/2017/02	Narrow pavement	Junction of Main Street and Pond Lane	Greetham	Completed	
ITCP/2017/03	Narrow lane with no 'pull ins'	Cow Lane	Whissendine	Completed	
ITCP/2017/04	Safety concerns	The cross roads on Grantham Lane,	Empingham	No work required	No Works required, however the Parish did fund the installation of 4x junction warning signs on yellow backing and lining

ITCP/2017/05	Safety concerns	From the Ashwell Road junction, along Market Overton Road to the Mill Lane turning, then alongside Mill Lane as far as the school.	Cottesmore	Closed - no work required.	
ITCP/2017/06	Speeding	Junction with Fosse Lane, Thistleton Road and Main Street at the eastern end of the village from Witham Road.	Thistleton	Completed	
ITCP/2017/07	Speeding	A47	Glaston	No work required	
ITCP/2017/08	Speeding	Eastern entrance to village	Little Casterton	Completed	Installation of a chicane and associated signs and lines
ITCP/2017/09	Lack of footway/ cycleway - concern for safety and isolation.	Braunston to Oakham	Braunston and Oakham	Closed - strategic scheme to be considered under Local Cycling and Walking Infrastructure Plan	

ITCP/2017/10	Speeding	St Ebbas Close	Ryhall	Completed	Due to the constraints of the road being part of the abnormal loads network RCC installed pedestrian warning signs on the approach to St Eabbas Way and SLOW markings
ITCP/2017/11	Lack of footway/ cycleway - concern for safety and isolation.	Wood Lane crossroad to Stretton	Greetham and Stretton	Closed - strategic scheme to be considered under Local Cycling and Walking Infrastructure Plan	
ITCP/2017/12	Concerns regarding safety and isolation due to traffic volume and speed	A606	Langham	No work required	
ITCP/2017/13	Lack of dedicated cycle route	Lyndon Top	Manton	Progress or construct	Scheme is being finalised and costs put together. Works scheduled for 2024
ITCP/2018/01	Safety concerns for cyclists and pedestrians	Northern footway on the A6121, Ketton - approximately between Chater Lodge and The Gate Lodge.	Ketton	Progress or construct	Scheme in design stage and cost calculated. Scheme to go to Cabinet to be added to the capital programme

ITCP/2018/02	Speeding vehicles causing concern for safety	Littleworth Lane and New Road	Belton	Completed	
ITCP/2018/03	Speeding vehicles causing concern for safety	the A6121 (Main Street) and Casterton Lane	Tinwell	Completed	
ITCP/2018/04	Traffic management and civil enforcement review	Church Road and Empingham Road	Ketton	Completed	
ITCP/2018/05	Road safety concerns	Barrowden Road & the junction of Barrowden Road/Geeston Road	Ketton	Completed	
ITCP/2018/06	Lack of crossing point	Uppingham Road	Caldecott	No works required	
ITCP/2018/07	Lack of crossing point	A606	Empingham	No work required	No work required due to infrequent pedestrian movements
ITCP/2018/08	Concern regarding the roundabout	Seaton Road	Uppingham	No work required	
ITCP/2018/09	Lack of pedestrian route	Edith Weston Road	North Luffenham	No work required	
ITCP/2018/10	Accident cluster site	Wireless Hill roundabout	South Luffenham	Completed	

ITCP/2018/11	Speed Limit Review, road width and congestion.	Pickworth Road and Water Lane	Great Casterton	No work required	RCC looked at various issues raised by the parish council in a lengthy report completed 2019. The report concluded that the existing traffic calming measures are working as is, and there are no additional works proposed. Measures around the cross roads were suggested by the parish however these have not proceeded due to a number of reasons. Firstly, the land available to the highways authority is constrained by property boundaries and secondly, the narrow road of Water Lane discourages the majority of HGVs using this road. If this was widened HGVs will use this as a cut through more frequently
ITCP/2018/12	-	-	-	Merged or removed	
ITCP/2018/13	Volume of traffic and lack of pedestrian crossing point, speed of vehicles, bus pull ins	Various sites	Ryhall	Completed	A number of assessments were carried out at this location and it became evident that the residents wanted the large layby to remain as is. RCC therefore installed a suitable placed dropped kerb on Turnpike Road
ITCP/2018/14	-	-	-	Merged or removed	

ITCP/2018/15	-	-	-	Merged or removed	
ITCP/2018/16	-	-	-	Merged or removed	
ITCP/2019/01	Speeding on bend of road	Bend on Barnsdale Avenue/ Cottesmore Road - at the junction with Oakham Road.	Exton and Horn	Completed	
ITCP/2019/02	Plant growth narrowing road.	Bend on Station Road	Ketton	No work required	
ITCP/2019/03	Safety of children travelling to school	Main Street and Willoughby Drive	Empingham	Completed	RCC installed pedestrian warning signs on yellow backing and a chicane to reduce vehicle speeds on the approach to the Village on Main Street
ITCP/2019/04	Access for children using public transport	Bus Drop off outside Uppingham C of E primary school	Uppingham	Completed	RCC installed pedestrian warning signs on yellow backing and a chicane to reduce vehicle speeds on the approach to the Village on Main Street
ITCP/2019/05	Speeding	Junction of A47 and A6121	Morcott	No work required	
ITCP/2019/06	Speeding, pedestrian safety and bus stop access	A6121	South Luffenham	completed	

ITCP/2019/07	Speeding	Manor Road, Stocken Hall Road and Clipsham Road	Stretton	Completed	
ITCP/2019/08	Speeding, use of road as cut through and lack of pavement	Bowling Green Lane	Market Overton	Completed	
ITCP/2019/09	Road safety	Lyddington Road	Caldecott	On hold	
ITCP/2019/10	Speeding and overtaking	A47 between Barrowden and Duddington - particularly in the area of the two junctions into Tixover village to the south and the road to Tixover Grange to the north.	Tixover	Completed	
ITCP/2019/11	Speeding	Braunston Road	Oakham	Completed	
ITCP/2019/12	Road safety	Lands' End Way (VAR Center)	Oakham	No work required	
ITCP-2019-13	Speeding	Teigh Rd/Cottesmore RD	Ashwell	Completed	
ITCP-2019-14	Parking	Stockerston Rd, from the School Theatre westwards	Uppingham	On hold	

ITCP-2019-15	Road safety	A6121 - both entrances to village and junction with Plover Road	Essendine	Completed	
ITCP-2019-16	Collision cluster site	A606 - Barnsdale	Barnsdale	Completed	
ITCP-2019-17	Collision cluster site	A606, Burley Park Way junction with Kestrel Road	Oakham	No work required	
ITCP-2019-18	Collision cluster site	A6121 Between Ryhall and Essendine	Ryhall and Essendine	Completed	
ITCP-2019-19	Collision cluster site	A606 - Normanton Park Road junction	Empingham	Completed	
ITCP-2019-20	Collision cluster site	Wireless Hill	South Luffenham	No work required	
ITCP-2019-21	Collision cluster site	High Street/ Burley Road junction	Oakham	No work required	
ITCP-2019-22	Collision cluster site	Park Lane/ Barleythorpe Road junction	Oakham	No work required	
ITCP-2019-23	Speeding and safety	Main Street	Lyddington	Completed	
ITCP-2019-24	Lack of disabled parking bay	Lammas Close	Braunston	Merged or removed	
ITCP-2019-25	Parked vehicles causing obstruction	Maresfield Road area (newly built estates)	Barleythorpe	Closed - duplicated enquiry	Duplicated enquiry - moved to ITCP-2021-08

ITCP-2019-26	Vehicles putting cyclists in danger	Thistleton Road, between Market Overton and Thistleton	Market Overton and Thistleton	Closed - strategic scheme to be considered under Local Cycling and Walking Infrastructure Plan	
ITCP-2019-27	Traffic: Vehicles are travelling too fast; Not enough time to cross the road; The road is being used as a rat run; There is no safe place to cross the road; Traffic is queueing at peak times.	Junction of High Street and Pit Lane	Ketton	No work required	
ITCP-2019-28	Speeding and safety concerns relating to junction of Farriers Reach.	Lands' End Way/ Farriers Reach	Oakham	Completed	

ITCP-2019-29	Safety of pedestrian crossing	Main Street	Barleythorpe	No work required	
ITCP-2019-30	Speeding traffic	Teigh Road, Road from Ashwell to Edmonthorpe. From the corner where there is a turn to Market Overton, past the 3 entrances to the village	Teigh	Closed - no work required.	
ITCP-2019-31	Speeding traffic	Road between Toll Bar towards Little Casterton	Little Casterton	Completed	Traffic calming measures were installed this included a new 40mph buffer zone <ul style="list-style-type: none"> •Removal of old 30mph and national speed limit signs and posts •Installation of new 30mph village sign plates on yellow backing boards •New 40mph and repeater speed
ITCP-2019-32	Speeding traffic	Village entrances on A6121 from Bourne and Stamford	Ryhall	Completed	RCC carried out works to improve southern gateway into Ryhall to match northern entrance on A6121. Works to
ITCP-2019-33	Speeding traffic	Both village entrances to Belmesthorpe	Belmesthorpe	No work required	include new village name plate, red high friction surfacing, 30mph roundel and dragon
ITCP-2019-34	Disabled parking bay	Derwent Drive	Oakham	Merged or removed	teeth

ITCP-2019-35	Parking	Lyndon Road	North Luffenham	No work required	
ITCP-2019-36	Parked vehicles causing obstruction	Huntsman Drive	Oakham	On hold	Parking and Engineers have been in communication with the police, residents group and school regarding this matter. The scheme is still on going until the road becomes adopted.
ITCP-2019-37	Parked vehicles are causing an obstruction	Burley Road, from Langham CofE Primary school to Ashwell Road	Langham	No work required	
ITCP-2019-38	Vehicles putting cyclists in danger	Braunston Road - Between roundabout and hill as you leave Oakham towards Braunston	Oakham	Merged or removed	
ITCP-2019-39	Road Safety	Live Hill and Luffenham Road, both roads into Barrowden from A47	Barrowden	Closed - no work required.	
ITCP-2019-40	Speeding traffic	Oakham road - bend at village entrance (from Oakham)	Braunston	Completed	
ITCP-2019-41	Junction alignment at Reeves Yard	Junction of Queens Street, Reeves Yard and South View	Uppingham	Closed - no work required.	

ITCP-2019-42	Lack of crossing point	Burley Park Way (by roundabout) towards Langham and the junction for Maresfield Road	Barleythorpe	Completed	
ITCP-2019-43	Safety and capacity issues at Uppingham bus interchange.	North Street East	Uppingham	Closed - no work required.	
ITCP-2019-44	Parking and perceived safety issues	Main Street incl Oakham Road and Stapleford Rd junctions, Ashwell Road inc Station Road junction, Cow Lane and the green.	Whissendine	On hold	
ITCP-2019-45	Speeding Traffic and pedestrian safety	40mph buffer zones on the A606	Empingham	Completed	Completed - installation of 40mph buffer zone on A606 heading towards Stamford
ITCP-2019-45b	Further feasibility to address pc comments.	Stamford Road	Empingham	Completed	Completed – installation of additional measures for the 40mph buffer zone. Including red HFS, 40mph roundel and dragon teeth

ITCP-2019-46	Speeding traffic and inconsiderate / dangerous parking	Various locations within Edith Weston	Edith Weston	Completed	
ITCP-2020-01	Speeding vehicles	Particularly but not confined to west end of Main Street	Seaton	No Works required	
ITCP-2020-02	Junction visibility - road safety concern	Junction of Woodside and Cottesmore Road	Ashwell	Completed	
ITCP-2020-03	Parking - vehicles causing obstruction	Wakerley Road, by village Hall	Barrowden	No work required	
ITCP-2020-04	Speeding traffic and pedestrian safety	Church Lane and corner Main Street (West End side)	Greetham	Closed - no work required.	
ITCP-2020-05	Safety concerns over chicane priority sign	Main Street outside village shop/village green	Greetham	Completed	

ITCP-2020-06	Road Safety - request for footway LHS of carriageway	Geeston settlement carriageway	Ketton	Progress or construct	Going through design. Officers have carried out early contractor involvement (ECI) and have instructed openreach to attend site to survey the BT chamber. An order has been raised with BT to carry out the assessment. RCC are now waiting for the assessment by BT to be completed
ITCP-2020-07	Safety concerns - cyclists not using cycleway provided. Speeding vehicles and parking in laybys.	Junction of Church Road and Hambleton Road	Egleton	Closed - no work required.	
ITCP-2020-08	Lack of bus stop	Turn into Egleton village from the A6003	Egleton	Closed - no work required.	
ITCP-2020-09	Pedestrian safety - lack of connecting footways	Ashwell Road (from the roundabout and the Veterinary surgery)	Oakham	Closed - strategic scheme to be considered under Local Cycling and Walking Infrastructure Plan	

ITCP-2020-10	Parked vehicles causing obstruction	Kings Road	Oakham	No work required	
ITCP-2020-11	Road safety - speeding vehicles within school 20mph zone.	Burley Road outside of Oakham C of E	Oakham	Closed - No works required	
ITCP-2020-12	Parked vehicles causing obstruction	Willow Crescent	Oakham	No works required	
ITCP-2020-13	Road safety - speeding vehicles and signage concerns	Mount Pleasant on Uppingham Road	Oakham	Closed - no work required.	
ITCP-2020-14	Road safety - pedestrian footway too narrow.	Section of footway running from Lonsdale House to LIDL along Main Road.	Barleythorpe	Completed	
ITCP-2020-15	Speeding traffic and pedestrian safety	40mph buffer zones on the A606 - Stamford entrance	Empingham	Merged or removed	Merged or removed – duplicated concern ITCP-2019-45

ITCP-2020-16	Lack of cycle way through village	Manton village to existing cycleway near Chater Road	Manton	Closed - strategic scheme to be considered under Local Cycling and Walking Infrastructure Plan	
ITCP-2020-17	Accessibility - lack of dropped kerb	North side of Rogues Lane, opposite the recently installed bus stop/shelter	Cottesmore	Completed	
ITCP-2020-18	Parked cars causing obstruction and speeding traffic	Princess Avenue	Oakham	No work required	
ITCP-2020-19	Speeding vehicles, including lorries, causing safety concern	Main roads through Edith Weston - including Normanton Road, Manton Road and Pennine Drive	Edith Weston	Closed - no work required.	
ITCP-2020-20	Speed of vehicles causing a safety concern	Wing Hill, Top Street and Morcott Road	Wing	Closed - No works required	

ITCP-2020-21	Lack of footway - concern for safety	Short section of B672 to footway along A47.	Morcott	Closed - no work required.	It is not recommended to install a footpath at this location. This road leads to 2 dwellings in open countryside. The road is within a 30mph limit with wide grass verges. Pedestrians are able to step off the road onto the verge if a vehicle approached.
ITCP-2020-22	Speed of vehicles combined with shared road usage - concern for safety.	Egleton turn to Manton	Egleton and Gunthorpe	Closed - strategic scheme to be considered under Local Cycling and Walking Infrastructure Plan	
ITCP-2020-23	Road safety	Spinney Hill	Oakham	Merged or removed	
ITCP-2020-24	Speeding	Village	Cottesmore	Completed	
ITCP-2020-25	Speeding	Garden Road, Empingham and Stamford Road	Exton	Closed - No works required	
ITCP-2020-26	Speeding/ road alignment	A6003	Caldecott	Completed	
ITCP-2020-27	Pedestrian safety	A606, Main Road	Langham	Feasibility and design	Scheme approved for construction and will tie into Active Travel Rutland. The scheme is currently being designed by Aecom

ITCP-2020-28	Speeding	The roads immediately outside the village limits at the Oakham and Knossington ends of the village.	Braunston in Rutland	Merged or removed	
ITCP-2020-29	Speeding and overtaking	Luffenham Road, Stamford Road and Empingham Road	Ketton	Closed - No works required	
ITCP-2020-30	Skid resistance	A47 Leicester Road (Site 774, 850 & 5721)	Uppingham	Merged or removed	
ITCP-2020-31	Speeding	Bypass, near Alsthorpe Road junction	Oakham	Closed - No works required	
ITCP-2020-32	Road safety	Thorpe by Water - bend (X : 490122 Y: 297128)	Thorpe by Water	Closed - No works required	
ITCP-2020-33	KSI site	B1081 junction with A1 south bound slip road	Great Casterton	No work required	KSI was not due to road layout or condition.
ITCP-2020-34	KSI site	A6003 north of Manton	Manton	Completed	
ITCP-2020-35	Skid resistance	A6121 Turnpike Road (site 2271)	Ryhall	Merged or removed	
ITCP-2020-36	Skid resistance	A6003 Oakham Road (sites: 4610/5790)	Preston	Merged or removed	

ITCP-2020-37	Skid resistance	A6121 Stamford Road (sites: 5157/2692)	Ryhall	Merged or removed	
ITCP-2020-38	Skid resistance	A6121 Turnpike Road (site 5303)	Ryhall	Merged or removed	
ITCP-2020-39	Skid resistance	B668 Stretton Road (site 565)	Greetham	Merged or removed	
ITCP-2020-40	Skid resistance	B664 North Street West (site 2892)	Uppingham	Merged or removed	
ITCP-2020-41	Skid resistance	B640 High Street (site 2952)	Oakham	Merged or removed	
ITCP-2020-42	Skid resistance	B640 High Street (sites 2982/2457/3288)	Oakham	Merged or removed	
ITCP-2020-43	Skid resistance	B672 New Road (site 6402)	Thorpe by Water	Merged or removed	
ITCP-2020-44	Skid resistance	C1002 Whissendine Road (site 63)	Ashwell	Merged or removed	
ITCP-2020-45	Skid resistance	C1010 Manton Road (site 615)	Edith Weston	Merged or removed	
ITCP-2020-46	Skid resistance	C1018 Station Road (site 1218)	South Luffenham	Merged or removed	
ITCP-2020-47	Skid resistance	C1019 Cottesmore Road (site 1700)	Exton	Merged or removed	

ITCP-2020-48	Skid resistance	C1010 Wytchley Warren Lane (site 1900)	Normanton	Merged or removed	
ITCP-2020-49	Skid resistance	C1002 Ashwell Road (site 1956)	Cottesmore	Merged or removed	
ITCP-2020-50	Skid resistance	C1009 Loddington Lane (site 2229/5064)	Belton	Merged or removed	
ITCP-2020-51	Skid resistance	C1004 Cold Overton Road (site 2285/2418)	Oakham	Merged or removed	
ITCP-2020-52	Skid resistance	C1008 Horn Lane (site 2432)	Empingham	Merged or removed	
ITCP-2020-53	Skid resistance	C1002 Ashwell Road (site 2673)	Cottesmore	Merged or removed	
ITCP-2020-54	Skid resistance	C1005 Braunston Road (site 3250)	Oakham	Merged or removed	
ITCP-2020-55	Skid resistance	C1006 The Wisp (site 3470)	Braunston	Merged or removed	
ITCP-2020-56	Skid resistance	C1012 Wing Road (site 3482)	Preston	Merged or removed	
ITCP-2020-57	Skid resistance	C1018 Wireless Hill (site 4068)	South Luffenham	Merged or removed	
ITCP-2020-58	Skid resistance	C1013 Grantham Lane (sites 4864/6251/2747)	Empingham	Merged or removed	

ITCP-2020-59	Skid resistance	C1002 Ashwell Road (site 5454)	Cottesmore	Merged or removed	
ITCP-2020-60	Skid resistance	C1005 Knossington Road (site 5773)	Braunston	Merged or removed	
ITCP-2020-61	Skid resistance	C1002 Ashwell Road (site 6142)	Whissendine	Merged or removed	
ITCP-2020-62	KSI site	Wing Road	Glaston	No work required	
ITCP-2020-63	KSI site	C9304 Ryhall Road	Ryhall	No work required	
ITCP-2020-64	KSI site	C5305 High Street	Oakham	No work required	
ITCP-2020-65	KSI site	A47 Peterborough Road, junction with Barrowden Lane	Barrowden	Completed	
ITCP-2020-66	KSI site	Braunston Road	Oakham	No work required	
ITCP-2020-67	KSI site	B664 North Street West, junction with Stockerston Road	Uppingham	No work required	
ITCP-2020-68	KSI site	C9304 Ryhall Road on bend near Salters Lane	Little Casterton	No work required	KSI was not due to road layout or condition.

ITCP-2020-69	KSI site	A6121 Stamford Road, 400m north east of Station Road	South Luffenham	No works required	
ITCP-2020-70	KSI site	A6003 - bridge between Manton and Preston	Manton	Completed	
ITCP-2020-71	Cycleway footway provision	Ayston Road	Uppingham	On Hold	
ITCP-2020-72	Cycleway footway provision	Burley Road	Oakham	Completed	
ITCP-2020-73	Cycleway footway provision	Enhancements to existing cycleway footway on the A6121, Ketton - approximately between Chater Lodge and The Gate Lodge. Plus Tinwell to Stamford	Ketton and Tinwell	In feasibility	
ITCP-2020-74	Cycleway footway provision	Stamford towards Empingham (via Stamford Road).	Empingham	On Hold	On Hold through LCWIP
ITCP-2020-75	Speeding	Main Road	Barleythorpe	No Works required	

ITCP-2020-76	Speed and volume of traffic including HGVs	Lyndon Road and Wing Road	Manton	Closed - No works required	Vehicles are complying with the stated speed limit and the existing speed limits are inline with the Department for Transport Circular Setting Local Speed Limits
ITCP-2020-77	Lack of crossing point on cycleway	between Cottesmore and Greetham	Cottesmore and Greetham	Closed - no work required.	
ITCP-2020-78	KSI site	B668 Greetham Road, junction with Wood Lane	Stretton	Closed - no work required.	
ITCP-2020-79	KSI site	C5306 Loddington Lane	Belton	No work required	
ITCP-2020-80	KSI site	A6003 - farm entrance between Uppingham and Preston	Ayston	No work required	
ITCP-2020-81	Roadside parking area	Lyddington Road	Caldecott	Progress or construct	The scheme has been designed and costs calculated. Order has been raised with the contractor with estimated completed by date of 31/3/2024
ITCP-2021-01	Narrow footway	outside Exeter Arms, Leicester Road	Uppingham	No Works required	
ITCP-2021-02	Speeding traffic	Maresfield Road	Barleythorpe	On Hold	Awaiting Adoption of road before progressing with concern.

ITCP-2021-03	Speeding vehicles (including cyclists)	Village entrance - approaching from Holywell	Pickworth	Closed - No works required	
ITCP-2021-04	Speeding	Pennine Drive from the junction with Normanton Road to Welland Road and the gate onto the North Luffemham airfield	Edith Weston	Closed - No works required	
ITCP-2021-05	Inconsiderate parking	Various locations within Aldgate	Ketton	On Hold	
ITCP-2021-06	Speeding traffic	Various locations within village	Ashwell	Initial assessment	Undergoing the initial assessment, collecting data and site visits. Ashwell is carrying out a community speed watch in September 2023 which can feed into this route.
ITCP-2021-07	Safety concern	Bus shelter on A6003	Preston	Progress or construct	A scheme has been put together including improved signs and lines. This has been approved by the Parish. Estimate complete date December 2024
ITCP-2021-08	HGV traffic and parking	Maresfield Road	Barleythorpe	On Hold	Awaiting Adoption of road before progressing with concern.
ITCP-2021-09	Lack of parking	Brooke Road	Braunston	Merged or removed	

ITCP-2021-10	Lack of walking route	Mill Lane	Cottesmore	Merged or removed	
ITCP-2021-11	Speeding trafficking	Princess Avenue and surrounding roads	Oakham	Closed - No works required	
ITCP-2021-12	Speeding	A6121 on the south-western outskirts of village	Ketton	No works required	Assessment has been completed. No works are proposed as vehicles are complying to a suitable speed limit.
ITCP-2021-13	Parked cars blocking Fire Engine access	Lyndon Rd,(South end) Hambleton Peninsular	Hambleton	Completed	Double yellow line scheme was recommend, approved and implemented.
ITCP-2021-14	Lack of footpath with dropped kerb to cross	Lands End Way (LE15 6US area)	Barleythorpe	Progress or construct	Scheme has been designed and costed. Awaiting confirmation from Allison Homes for when the footpath will be completed to the north of Farriers Reach junction with Lands End Way. The two footpaths will tie in together
ITCP-2021-15	Speeding	Edith Weston Road	North Luffenham	Closed - duplicated enquiry	This enquiry has been duplicated and has now been assessed under ITCP-2022-28 in correspondence with police

ITCP-2021-16	Safety of pedestrians/ cyclists	Belmesthorpe Lane	Ryhall	Closed - no work required.	RCC have already installed various measures along this route, including gateways, village name plate and a reduced speed limit with repeater signs. The road has good forward visibility and there have been no recorded accidents. It is proposed not to carry out any further measures in this location as the road is in open countryside and therefore any additional work/new footpaths would not be in keeping with the local area.
ITCP-2021-17	Lack of parking/ traffic flow	Burley Road	Oakham	Closed - no work required.	
ITCP-2021-18	Speeding and unsafe overtaking on this stretch of road	Stretch of the B668 running through Burley from Burley Forge to Burley Water Tower	Burley	Completed	
ITCP-2021-19	Speeding traffic and assessment for traffic calming measures	: Entry to Seaton village from Uppingham where Main Street becomes narrow and bends.	Seaton	Merged or removed	
ITCP-2021-20	Lack of dropped kerb	B664	Uppingham	Completed	

ITCP-2021-21	Speeding / safer footpath between villages	Belmesthorpe Road,	Rhyall	Merged or removed	Merged with ITCP-2021-16 as this was a duplicated request. Both concerns for this and ITCP-2021-16 were the same
ITCP-2021-22	Road surface dressing and traffic calming	Rutland Way, Church Street, The Square and New Road Ryhall	Ryhall	Closed - no work required.	There were a number of responses regarding - please request ITCP initial assessment from Highways@rutland.gov.uk
ITCP-2021-23	Narrow footway	Barleythorpe main Road	Barleythorpe	No works required	
ITCP-2021-24	KSI site	Teigh Rd, Ashwell	Teigh	No works required	
ITCP-2021-25	PROW Bridge Stability	End of Pringle Lane	Morcott	Completed	
ITCP-2021-26	KSI	Hooby Lane	Greetham	No works required	
ITCP-2021-27	Dangerous camber	Footpath E108	Market Overton	Awaiting initial assessment	
ITCP-2021-28	Lack of unobstructed footway	Adjacent to Langham Place Cottages, Ashwell to Oakham	Ashwell	Initial assessment	Undergoing the initial assessment, collecting data and site visits.
ITCP-2021-29	Parking Issues	King Road, Oakham	Oakham	Merged or removed	
ITCP-2021-30	Footpath improvement / disabled access	Windermere Road, Crummock Avenue, Coniston Road	Edith Weston	On hold	

ITCP-2021-31	KSI site	Ryhall Rd, Grt Casterton	Great Casterton	No works required	KSI was not due to road layout or condition.
ITCP-2021-32	KSI site	Wenton Close Jnc Ashwell Rd Cottesmore	Cottesmore	No works required	
ITCP-2021-33	Concern regarding accidents	Ashwell Village crossroads	Ashwell	Progress or construct	Proposal to replace 4x giveaway signs with 4x giveaway signs on yellow backing to make it more visible. The white lines have already been refreshed through the lining programme. Order raised with contractor, estimated completed Date Novemeber 2023
ITCP-2021-34	Parking	Langham Place cottages adjacent to Rutland Garden Centre	Ashwell	Merged or removed	
ITCP-2021-35	Parking Sign needs moving	LE15 7 traffic sign adjacent to Ashwell Village Hall, Oakham Rd, Ashwell	Ashwell	Completed	
ITCP-2021-36	Concern that crossing is abused by people / vehicles	LE15 9QJ The crossroads at the junction of Orange St, Ayston Rd, and North Street East and West	Uppingham	No works required	

ITCP-2021-37	Vehicles are travelling too fast;Not enough time to cross the road;There is no safe place to cross the road	Main St	Thistleton	Initial assessment	
ITCP-2021-38	Lack of safe crossing point	junction of Langham Rd and Oakham Rd in Ashwell	Ashwell	Progress or construct	An assessment has been carried out which identified there is no dropped kerb in this area, therefore it is recommended to provide a drop kerb. Order Raised with contractor, estimated complete date January 2024
ITCP-2021-39	Lack of safe crossing point	Crossing into Langham Rd, and out of Langham Rd onto the footpath in Oakham Rd	Ashwell	Closed - duplicated enquiry	
ITCP-2021-40	Accident site	Bend and hilltop on road from Langham to Whissendine	Langham / Whissendine	Completed	
ITCP-2021-41	KSI Site	A47 LEICESTER ROAD AYSTON BETWEEN WARDLEY & AYSTON.	Ayston	No works required	

ITCP-2021-42	Vehicles travelling too fast	Main Street and Stretton Rd Greetham	Greetham	Closed - No works required	Initial assessment was completed. This identified that there is not a speeding issue and vehicles are complying to the stated speed limit. The speed limits are positioned at the most suitable locations through the village.
ITCP-2021-43	Narrow bridge - a road safety concern for oncoming traffic	Narrow bridge at OS 877137 Cottesmore Bridge in Cottesmore Road, Ashwell	Ashwell	Completed	Advance warning sign of road narrowing is provided on Cottesmore side of bridge but not Ashwell. Proposal to add 1 x sign and post on Ashwell approach to bridge. Works completed 11/9/2023
ITCP-2021-44	Dangerous junction for cars pulling out of Barrow	The Barrow turn on the Cottesmore to Market Overton Road LE15 7PE	Barrow	Closed - No works required	Initial assessment and site visit was completed. There is suitable visibility in both directions when exiting Barrow and there have been no recorded accidents. It is therefore recommended that no works are required
ITCP-2021-45	The bus shelter is in a very poor state of repair	New road, Clipsham	Clipsham	Completed	

ITCP-2021-46	Parking Safety	Entrance to the Community Centre at the junction of Main St/The Leas outside the Sun Inn	Cottesmore	Closed - No works required	No works are required. There is sufficient parking in the local area. Parking carried out numerous surveys in this area during peak periods, such as football matches and fireworks night. Therefore the enquiry has been closed down
ITCP-2021-47	Traffic speeding through the village	Traffic through the Main street in Clipsham particularly in the west to east direction.	Clipsham	Closed - No works required	
ITCP-2021-48	Request for two pedestrian crossings in village	Northbrook Close / Locks Close and near 66 Main Street	Greetham	Closed - No works required	An assessment was carried out in accordance with Local Transport Note 1/95. Due to low pedestrian numbers it is not recommended to install formal pedestrian crossings in Greetham
ITCP-2021-49	KSI site	C8407 GLASTON ROAD UPPINGHAM AT ENTRANCE TO GARDEN CENTRE	Uppingham	No Works required	
ITCP-2021-50	Speed Limit Review	20mph areas within village	Morcott	initial Assessment	Enquiry to Parish and Ward Member to relocate 20mph limit and provide a 30mph buffer. Further correspondence with Parish on 1/9/2023 who will be looking into this matter.

ITCP-2021-51	Parking - loading vehicles causing an obstruction	Pond Lane, Greetham. Opposite side entrance to Oak House Residential Home	Greetham	Closed - No works required	
ITCP-2021-52	Existing traffic calming measures looking worn	Chicanes at North and South ends of Main Street (Old Great North Road)	Great Casterton	No Works required	The parish council have reported that the chicane is looking worn. The chicane is working as proposed and conforms to the TSRGD standards. This is purely cosmetic and therefore any additional works could be funded by the parish
ITCP-2021-53	KSI Site	Wheatley Av, Uppingham	Uppingham	No works required	
ITCP-2021-54	Speed Limit Review	20mph areas within village	South Luffenham	initial Assessment	Enquiry to Parish and Ward Member to relocate 20mph limit and provide a 30mph buffer. Further correspondence with Parish on 29/7/2023 who will be discussing this matter at the next PC meeting and will provide RCC with a response
ITCP-2021-55	Speed Limit Review	20mph areas within village	Bisbrooke	Closed - No works required	The PC feel the 20mph limits are in the most suitable location for the village, given the narrow and twisty roads as soon as you enter the village. Therefore the 20mph limit will remain as is.

ITCP-2021-56	Concern regarding accidents / road surface	A6003 The location is 1.3 miles from the end of Uppingham 30mph speed limit and 1.8 miles from the Caldecott 40mph sign on the A6003	Uppingham and Caldecott	No works required	
ITCP-2021-57	Speeding	Highfields Close/ Exton Road	Empingham	Closed - No works required	Closed - No works required A speed survey was carried out which showed vehicles were complying with the stated speed limit. This was circulated to the Parish Council 17/11/2022
ITCP-2021-58	KSI site	Barnsdale Avenue, Exton, Rutland	Exton	No Works required	
ITCP-2021-59	KSI	C8236 MANTON ROAD EDITH WESTON APPROX 150M W EDITH WESTON ROAD	Edith Weston	No works required	KSI site

ITCP-2021-60	KSI	C5305 KNOSSINGTON ROAD BRAUNSTON APPROX 100M E THE WISP.	Braunston	No works required	KSI site
ITCP-2021-61	KSI	A47 GLASTON ROAD MORCOTT JW ROAD TO MORCOTT VILLAGE.	Morcott	No works required	KSI site
ITCP-2021-62	Collapsed Bridge	E105 South West of Market Overton	Market Overton	Completed	
ITCP-2021-63	Safety concern - road surface	A6003 Uppingham to Caldecott - what 3 words: shift/unfocused/pur sue.	Caldecott	No Works required - this has been completed through the resurfacing programme	
ITCP-2022-01	Narrow pavement. Speeding.	Clipsham Road	Stretton	Feasibility and design	A speed survey highlighted high vehicle speeds and officers will put together a feasibility design for further traffic calming measures.
ITCP-2022-02	Existing traffic calming measures looking worn	Old Great North Road, Great Casterton	Great Casterton	Closed - duplicated enquiry	Please see ITCP-2021-52

ITCP-2022-03	Lack of parking	Allotment and play park on Burley Road	Langham	On Hold	
ITCP-2022-04	KSI Site	A6121 SOUTH LUFFENHAM ROUNDABOUT WITH STATION ROAD	South Luffenham	No Works required	KSI site
ITCP-2022-05	KSI Site	LANDS END WAY BARLEYTHORPE JW HACKAMORE WAY.	Barleythorpe	No Works Required	KSI site
ITCP-2022-06	bus stop infrastructure	Countywide	Countywide	Awaiting initial assessment	
ITCP-2022-07	Extension to 30mph zone	Little Casterton Road	Great Casterton	Closed - No works required	The Parish have requested an extension of the 30mph zone on Little Casterton Road. The Police would not support this proposal at present and therefore no works are required.
ITCP-2022-08	30mph speed limit requested	Church Road	Egleton	Closed - no works required	As there are no accidents and no evidence of excessive speed, a speed reduction in this area would not be supported by RCC or the police and therefore no recommended.

ITCP-2022-09	30mph speed limit requested	Hambleton Road	Egleton	Closed - no works required	As there are no accidents and no evidence of excessive speed, a speed reduction in this area would not be supported by RCC or the police and therefore no recommended.
ITCP-2022-10	Speeding vehicles	Junction of Gretton Street and Farrers Way	Barleythorpe	on hold	Awaiting Adoption of road before progressing with concern.
ITCP-2022-11	Speeding Traffic	Knossington Road, Braunston	Braunston	Closed - No works required	
ITCP-2022-12	Road signage to warn of flooding	Whissendine main St, Cow Lane, The Nook	Whissendine	Completed	Order has been raised
ITCP-2022-13	KSI site	A47 Barrowden	Barrowden	Closed - No works required	KSI Site
ITCP-2022-14	Accessability of public footpath PROW	Back Road	Barrowden	Initial Assessment	
ITCP-2022-15	Speeding	Back Road	Rhyall	Closed - No works required	An assessment was carried out on Back Road which showed there was not a speeding issue. The initial assessment was sent to the PC on 17/11/2022
ITCP-2022-16	Bus Layby & Shelter	Uppingham Road, Oakham	Oakham	Awaiting initial assessment	

ITCP-2022-17	2.5 Section of cycleway	Uppingham Road, Oakham	Oakham	Awaiting initial assessment	
ITCP-2022-18	Lack of dropped Crossings	Edmonton Way Estate, Oakham	Oakham	Progress or construct	There are no dropped kerbs around development. It is proposed to install 8 new dropped crossing around Edmonton Way. Estimated Complete date January 2024
ITCP-2022-19	Speeding - request for SIDS	Barleythorpe	Barleythorpe	Awaiting initial assessment	Parish wish to fund the SID themselves using CIL money. Matter to be discussed at HTWG.'
ITCP-2022-20	Signage Issue	A47 Wardley turn	Wardley	Completed	Order has been raised for 1xhorse warning sign on both approaches to Bridleway on A47. Works completed 13/9/2023
ITCP-2022-21	KSI	Main Street Lyddington	Lyddington	Closed - No works required	KSI Site
ITCP-2022-22	Noise associated with traffic and speeding	A6003/ London Road - Spring Back Way to Uppingham community college	Uppingham	Progress or construct	Following damage to the pedestrian barrier, it is recommended to remove this length of barrier and replace barrier with a new spec. The works will include footpath resurfacing and edging back. Estimated complete by date December 2024
ITCP-2022-23	KSI	A1 NB at on-slip with A606 Empingham Road, Stamford, Leics	Stretton	Closed - No works required	KSI Site

ITCP-2022-24	KSI	A1 Northbound prior to slip to B668	Stretton	Closed - No works required	KSI Site
ITCP-2022-25	Cycleway footway provision	Lyndon Road	Manton	Strategic	Strategic scheme to provide an off road cycleway. May be delivered through LCWIP.
ITCP-2022-26	Roundabout layout and lack of signage	Chater Close/ Lyndon Road	Manton	Progress or construct	RCC met with the parish council and ward members to discuss the concern in more detail. Following this officers met with the police on site to assess what could be achieved to improve the safety of this roundabout. A scheme has been recommended in consultation with the police and is recommended for construction. An order has been raised with estimated complete by date 30/1/2024
ITCP-2022-27	Request for yellow lining	Norton Street	Uppingham	On Hold	Informal signs up and will be monitored by officers. The Town Council have been involved in communications around this site.

ITCP-2022-28	Speed survey request	Edith Weston Road - The Oval	North Luffenham	Feasibility and design	A speed survey was carried out and showed vehicles are travelling in excess of the stated speed limit. Measures are being proposed. It should be noted that the Limit on Edith Weston Road is not a suitable limit as it does not comply with the DfT guidance for speed limit.
ITCP-2022-29	KSI 15/6/2022	B668 Stretton Road, Greetham	Greetham	Closed - No works required	KSI Site
ITCP-2022-30	KSI 8/5/2022	Manton Road, Edith Weston	Edith Weston	Closed - No works required	KSI Site
ITCP-2022-31	request for Traffic Speed Survey	A6003 into Caldecott	Caldecott	Closed - No works required	A speed survey has been carried out in Caldecott and it showed vehicles are complying with the speed limit. Therefore no works are required
ITCP-2022-32	Request for speeding enforcement	Greetham	Greetham	Closed - No works required	The speed limits through Greetham are set at appropriate locations complying with Police guidance and the Department for Transport Setting Local Speed Limits. Therefore no works are recommended to reposition the speed limit
ITCP-2022-33	KSI 18/11/2022	A47 Nr Belton	Belton	Closed - No works required	KSI Site

ITCP-2022-34	Road markings	Park View Estate	Ketton	Closed - No works required	There have been no recorded accidents. Street lining is removed within an estate to help reduced vehicle speeds as drivers are more cautious
ITCP-2022-35	Parked Cars	The Green	Exton	Closed - No works required	The Parish Council discussed this on 6/9/2023 at the Parish Council Meeting. The parish have advised that they will carry out engagement with the vilage hall, pub etc. to try and alleviate the parking problem, rather than physical measures.
ITCP-2022-36	Speeding	A606	Exton	Closed - No works required	Additional measures at Barnsdale were installed in 2019. Since the installation of the measures there have been no recorded accidents
ITCP-2022-37	KSI	Seaton Rd, Bisbrooke	Bisbrooke	No work required	
ITCP-2022-38	KSI	A1 Slip, Stretton	Stretton	No works required	The KSI happened on part of National England network and therefore would be assessed by National England
ITCP-2023-01	Road Safety	Railway Crossing/Cold Overton Road LE15 6LN	Barleythorpe	Progress or construct	Initial assessment completed. The LHA can not provide engineering solutions for reckless driving the barrier is closed, however can install a yellow box to prevent vehicles blocking the right hand turn lane. Order has been raised with contractor Estimated complete date January 2024

ITCP-2023-02	Parked Cars	Blacksmiths Avenue	Barleythorpe	Closed - no works required	This is a neighbourhood dispute based enquiry. The residents have been spoken to regarding parking locations.
ITCP-2023-03	Road Safety	Little Casterton Village	Little Casterton	Feasibility and design	The junctions have been assessed by RCC and the police and have suitable visibility splays and signage. It was noted during the site visit that the weight restriction signs are incorrectly placed and therefore it is recommended to have these relocated. This has included consultation with Lincs Highways, National England and the Police
ITCP-2023-04	Road Safety	A6003 Through Gunthorpe	Gunthorpe	Feasibility and design	Initial assessment completed. There is not a speeding issue through Gunthorpe and the speed limit is appropriate for the road. It is proposed to install 2x junction warning signs on the approach to Gunthorpe
ITCP-2023-05	Road safety	Clipsham to Stretton Rd	Clipsham	Initial Assessment	
ITCP-2023-06	Speeding Traffic	Whitwell A606 nr LE15 8BN	Whitwell	Awaiting initial assessment	

ITCP-2023-07	Make road a pedestrian only route	Crown Lane, Barrowden	Barrowden	Initial Assessment	The Parish wish to proceed with exploring the options of making Crown Lane a pedestrian route. To apply to pedestrianise a highway the Council must submit a Section 249 under the Town and Country Planning Act 1990 to the DfT.
ITCP-2023-08	Road Safety	Fleetwood Court, Stretton	Stretton	Feasibility and design	RCC have engaged with the prison and they will be updating information provided further correspondence to staff/contractors and visitors to remind them of the 30mph speed limit.
ITCP-2023-09	Road Safety	Belmesthorpe	Belmesthorpe	Initial assessment	Initial meeting carried out with Belmesthorpe Parish Meeting and Ward members 23/8/2023 to look at options for the village. Proposal were put to the police. Further assessments of the village are required
ITCP-2023-10	KSI	A606 Langham	Langham	No works required	No Works are required. The accident happened due to drivers being dazzled by the sun.

ITCP-2023-11	Speed Limit	Burley Road, Langham	Langham	Awaiting initial assessment	This speed limit proposal was previously looked at in 2017, however scheme did not proceed due to lack of parish support. A new assessment is required due to how long it has been since the 2017 review.
ITCP-2023-12	Speed Indicator Relocation	A606, Langham	Langham	Awaiting initial assessment	Enquiry to parish to provide more information as to where they would want SID relocating to and why.
ITCP-2023-13	Speeding Traffic	Cottesmore Road, Burley	Burley	Enquiry to police regarding speed limit reduction	
ITCP-2023-14	KSI	Bourne Rd, Essendine	Essendine	No Works required	No Works required - the accident did not occur due to highway defects
ITCP-2023-15	KSI	Oakham Road, Ashwell	Ashwell	No works required	No Works required - the accident did not occur due to highway defects
ITCP-2023-16	Parking	Medical Centre, Main Street Empingham	Empingham		
ITCP-2023-17	Uppingham 2023 Parking Charges	Uppingham	Uppingham		
ITCP-2023-18	Dangerous junction	Various junctions along bypass	Oakham	Awaiting initial assessment	
ITCP-2023-19	Dangerous footpath/board walk	E160	Exton	Awaiting initial assessment	

ITCP-2023-20	Pavement Accessibility	High Street East	Uppingham	Awaiting initial assessment	
ITCP-2023-21	Pavement Accessibility	Queen's Street	Uppingham	Awaiting initial assessment	
ITCP-2023-22	Pavement Accessibility	Various locations of dropped kerbs around Town Centre	Uppingham	Feasibility and design	RCC officers carried out a site visit with ward members and the Town Council and identified a few areas where the dropped kerbs require improvement. Progress to feasibility and design stage.
ITCP-2023-23	Speed of vehicles	Teigh Village	Teigh	awaiting initial assessment	
ITCP-2023-24	Speed of vehicles	Ingthorpe Village	Tinwell	Awaiting initial assessment	
ITCP-2023-25	Speed of vehicles with 20mph limit	Bisbrooke Village	Bisbrooke	Awaiting initial assessment	
ITCP-2023-26	Speed of Vehicles	Steadfold Lane	Ketton	Awaiting initial assessment	

ITCP-2023-27	Speed of vehicles	Manton Road	Edith Weston	Progress or construct	An assessment was carried out on site with the police following high readings from the community speed watch (CSW) it is recommended to progress with a scheme either side of Weston Road to reduce vehicle speeds entering and exiting the village. Order has been raised, complete by date 31/3/2024
ITCP-2023-28	Bus Stop bench	Barleythorpe Road	Oakham	Progress or construct	An order has been raised with the contractor for the installation of the bench. Estimated complete by date 7/12/2023 (depending on delivery of the bench)
ITCP-2023-29	Narrow Road and volume of traffic	Tixover Grange to Barrowden Rd Jnc	Tixover	Awaiting initial assessment	
ITCP-2023-30	Sign required	Barrowden Rd Jnc towards Cuckoo Farm	Tixover	Awaiting initial assessment	
ITCP-2023-31	Damage to property	Lyndon Rd North Luffenham	North Luffenham	Awaiting initial assessment	