

Reference	Concern	Location	Primary parish	Date application received	Status
ITCP/2016/06	Accident cluster site	Whissendine Road	Ashwell	30/06/2017	Completed
ITCP-2019-13	Speeding	Teigh Rd/Cottesmore RD	Ashwell	04/06/2019	Completed
ITCP-2020-02	Junction visibility - road safety concern	Junction of Woodside and Cottesmore Road	Ashwell	21/01/2020	Completed
ITCP-2020-44	Skid resistance	C1002 Whissendine Road (site 63)	Ashwell	12/10/2020	Merged or removed
ITCP-2021-06	Speeding traffic	Various locations within village	Ashwell	20/01/2021	Initial Assessment
ITCP-2021-28	Lack of unobstructed footway	Adjacent to Langham Place Cottages, Ashwell to Oakham	Ashwell	19/07/2021	Initial assessment
ITCP-2021-33	Concern regarding accidents	Ashwell Village crossroads	Ashwell	15/08/2021	Initial assessment
ITCP-2021-34	Parking	Langham Place cottages adjacent to Rutland Garden Centre	Ashwell	16/08/2021	Merged or removed
ITCP-2021-35	Parking Sign needs moving	LE15 7 traffic sign adjacent to Ashwell Village Hall, Oakham Rd, Ashwell	Ashwell	17/08/2021	Completed
ITCP-2021-38	Lack of safe crossing point	junction of Langham Rd and Oakham Rd in Ashwell	Ashwell	17/08/2021	Awaiting initial assessment
ITCP-2021-39	Lack of safe crossing point	Crossing into Langham Rd, and out of Langham Rd onto the footpath in Oakham Rd	Ashwell	17/08/2021	Closed - duplicated enquiry
ITCP-2021-43	Narrow bridge - a road safety concern for oncoming traffic	Narrow bridge at OS 877137 Cottesmore Bridge in Cottesmore Road, Ashwell	Ashwell	14/09/2021	Feasibility and design

ITCP-2020-80	KSI site	A6003 - farm entrance between Uppingham and Preston	Ayston	15/09/2020	No work required
ITCP-2021-41	KSI Site	A47 LEICESTER ROAD AYSTON BETWEEN WARDLEY & AYSTON.	Ayston	09/09/2021	No works required
ITCP/2016/17	Speeding	Main Road	Barleythorpe	23/09/2013	Completed
ITCP/2016/17 - REV	Speeding	Main Road	Barleythorpe	16/07/2019	No work required
ITCP-2019-25	Parked vehicles causing obstruction	Maresfield Road area (newly built estates)	Barleythorpe	25/07/2019	On hold
ITCP-2019-29	Safety of pedestrian crossing	Main Street	Barleythorpe	16/07/2019	No work required
ITCP-2019-42	Lack of crossing point	Burley Park Way (by roundabout) towards Langham and the junction for Maresfield Road	Barleythorpe	22/10/2019	Completed
ITCP-2020-14	Road safety - pedestrian footway too narrow.	Section of footway running from Lonsdale House to LIDL aong Main Road.	Barleythorpe	19/03/2020	Completed
ITCP-2020-75	Speeding	Main Road	Barleythorpe	16/11/2020	No Works required
ITCP-2021-02	Speeding traffic	Maresfield Road	Barleythorpe	02/02/2021	On Hold
ITCP-2021-08	HGV traffic and parking	Maresfield Road	Barleythorpe	16/02/2021	On Hold
ITCP-2021-14	Lack of footpath with dropped kerb to cross	Lands End Way (LE15 6US area)	Barleythorpe	19/04/2021	Progress or construct
ITCP-2021-23	Narrow footway	Barleythorpe main Road	Barleythorpe	10/06/2021	No works required
ITCP-2022-05	KSI Site	LANDS END WAY BARLEYTHORPE JW HACKAMORE WAY.	Barleythorpe	03/02/2022	No Works Required
ITCP-2022-10	Speeding vehicles	Junction of Gretton Street and Farrers Way	Barleythorpe	02/03/2022	on hold
ITCP-2022-19	Speeding - request for SIDS	Barleythorpe	Barleythorpe	20/05/2022	Awaiting initial assessment

ITCP-2023-01	Road Safety	Railway Crossing/Cold Overton Road LE15 6LN	Barleythorpe	09/01/2023	Initial assessment
ITCP-2023-02	Parked Cars	Blacksmiths Avenue	Barleythorpe	02/02/2023	Awaiting initial assessment
ITCP-2019-16	Collision cluster site	A606 - Barnsdale	Barnsdale	Accident Cluster Site	Completed
ITCP-2021-44	Dangerous junction for cars pulling out of Barrow	The Barrow turn on the Cottessmore to Market Overton Road LE15 7PE	Barrow	20/09/2021	Initial assessment
ITCP/2016/11	Speeding	Seaton Road	Barrowden	12/08/2014	Completed
ITCP-2019-39	Road Safety	Live Hill and Luffenham Road, both roads into Barrowden from A47	Barrowden	10/10/2019	Closed - no work required.
ITCP-2020-03	Parking - vehicles causing obstruction	Wakerley Road, by village Hall	Barrowden	24/01/2020	No work required
ITCP-2020-65	KSI site	A47 Peterborough Road, junction with Barrowden Lane	Barrowden	23/02/2020	Completed
ITCP-2022-13	KSI site	A47 Barrowden	Barrowden	10/05/2022	Closed - No works required
ITCP-2022-14	Accesibility of public footpath	Back Road	Barrowden	26/05/2022	Initial Assessment
ITCP-2019-33	Speeding traffic	Both village entrances to Belmesthorpe	Belmesthorpe	20/08/2019	No work required
ITCP/2018/02	Speeding vehicles causing concern for safety	Littleworth Lane and New Road	Belton	09/07/2018	Completed
ITCP-2020-50	Skid resistance	C1009 Loddington Lane (site 2229/5064)	Belton	12/10/2020	Merged or removed
ITCP-2020-79	KSI site	C5306 Loddington Lane	Belton	31/08/2020	No work required
ITCP-2022-33	KSI 18/11/2022	A47 Nr Belton	Belton	21/11/2022	Closed - No works required
ITCP-2021-55	Speed Limit Review	20mph areas within village	Bisbrooke	17/11/2021	Feasibility and design
ITCP-2022-37	KSI	Seaton Rd, Bisbrooke	Bisbrooke	31/01/2022	No work required

ITCP/2016/10	Speeding	Main Road	Braunston	01/12/2016	Completed
ITCP/2016/12	Speeding	Knossington Road/Main Road	Braunston	30/11/2016	Completed
ITCP-2019-24	Lack of disabled parking bay	Lammas Close	Braunston	17/07/2019	Merged or removed
ITCP-2019-40	Speeding traffic	Oakham road - bend at village entrance (from Oakham)	Braunston	17/10/2019	Completed
ITCP-2020-55	Skid resistance	C1006 The Wisp (site 3470)	Braunston	12/10/2020	Merged or removed
ITCP-2020-60	Skid resistance	C1005 Knossington Road (site 5773)	Braunston	12/10/2020	Merged or removed
ITCP-2021-09	Lack of parking	Brooke Road	Braunston	26/03/2021	Merged or removed
ITCP-2021-60	KSI	C5305 KNOSSINGTON ROAD BRAUNSTON APPROX 100M E THE WISP.	Braunston	08/12/2021	No works required
ITCP-2022-11	Speeding Traffic	Knossington Road, Braunston	Braunston	09/03/2022	Closed - No works required
ITCP/2017/09	Lack of footway/ cycleway - concern for safety and isolation.	Braunston to Oakham	Braunston and Oakham	13/11/2017	Closed - strategic scheme to be considered under Local Cycling and Walking Infrastructure Plan
ITCP-2020-28	Speeding	The roads immediately outside the village limits at the Oakham and Knossington ends of the village.	Braunston in Rutland		Merged or removed
ITCP-2021-18	Speeding and unsafe overtaking on this stretch of road	Stretch of the B668 running through Burley from Burley Forge to Burley Water Tower	Burley	17/05/2021	Completed
ITCP/2018/06	Lack of crossing point	Uppingham Road	Caldecott	12/09/2016	No works required
ITCP/2019/09	Road safety	Lyddington Road	Caldecott	25/05/2019	On hold

ITCP-2020-26	Speeding/ road alignment	A6003	Caldecott	16/08/2020	Completed
ITCP-2020-81	Roadside parking area	Lyddington Road	Caldecott	16/12/2020	Feasibility and design
ITCP-2021-63	Safety concern - road surface	A6003 Uppingham to Caldecott - what 3 words: shift/unfocused/pursue.	Caldecott	16/11/2021	No Works required - this has been completed through the resurfacing programme
ITCP-2022-31	request for Traffic Speed Survey	A6003 into Caldecott	Caldecott	15/11/2022	Initial assessment
ITCP-2021-45	The bus shelter is in a very poor state of repair	New road, Clipsham	Clipsham	20/09/2021	Feasibility and design
ITCP-2021-47	Traffic speeding through the village	Traffic through the Main street in Clipsham particularly in the west to east direction.	Clipsham	24/09/2021	Closed - No works required
ITCP-2023-05	Road safety	Clipsham to Stretton Rd	Clipsham	22/02/2023	Awaiting initial assessment
ITCP/2017/05	Safety concerns	From the Ashwell Road junction, along Market Overton Road to the Mill Lane turning, then alongside Mill Lane as far as the school.	Cottesmore	29/08/2017	Closed - no work required.
ITCP-2020-17	Accessibility - lack of dropped kerb	North side of Rogues Lane, opposite the recently installed bus stop/shelter	Cottesmore	23/03/2020	Completed
ITCP-2020-24	Speeding	Village	Cottesmore		Completed
ITCP-2020-49	Skid resistance	C1002 Ashwell Road (site 1956)	Cottesmore	12/10/2020	Merged or removed
ITCP-2020-53	Skid resistance	C1002 Ashwell Road (site 2673)	Cottesmore	12/10/2020	Merged or removed
ITCP-2020-59	Skid resistance	C1002 Ashwell Road (site 5454)	Cottesmore	12/10/2020	Merged or removed

ITCP-2021-10	Lack of walking route	Mill Lane	Cottesmore	19/03/2021	Merged or removed
ITCP-2021-32	KSI site	Wenton Close Inc Ashwell Rd Cottesmore	Cottesmore	09/08/2021	No works required
ITCP-2021-46	Parking Safety	Entrance to the Community Centre at the junction of Main St/The Leas outside the Sun Inn	Cottesmore	22/09/2021	Awaiting initial assessment
ITCP-2020-77	Lack of crossing point on cycleway	between Cottesmore and Greetham	Cottesmore and Greetham	19/11/2020	Closed - no work required.
ITCP-2022-06	bus stop infrastructure	Countywide	Countywide	12/02/2022	Awaiting initial assessment
ITCP-2019-46	Speeding traffic and inconsiderate / dangerous parking	Various locations within Edith Weston	Edith Weston	31/12/2019	Completed
ITCP-2020-19	Speeding vehicles, including lorries, causing safety concern	Main roads through Edith Weston - including Normanton Road, Manton Road and Pennine Drive	Edith Weston	07/05/2020	Closed - no work required.
ITCP-2020-45	Skid resistance	C1010 Manton Road (site 615)	Edith Weston	12/10/2020	Merged or removed
ITCP-2021-30	Footpath improvement / disabled access	Windermere Road, Crummock Avenue, Coniston Road	Edith Weston	25/06/2021	On hold
ITCP-2021-59	KSI	C8236 MANTON ROAD EDITH WESTON APPROX 150M W EDITH WESTON ROAD	Edith Weston	08/12/2021	No works required
ITCP-2022-30	KSI 8/5/2022	Manton Road, Edith Weston	Edith Weston	10/11/2022	Closed - No works required

ITCP-2021-04	Speeding	Pennine Drive from the junction with Normanton Road to Welland Road and the gate onto the North Luffemham airfield	Edith Weston	17/02/2021	Closed - No works required
ITCP-2020-07	Safety concerns - cyclists not using cycleway provided. Speeding vehicles and parking in laybys.	Junction of Church Road and Hambleton Road	Egleton	09/03/2020	Closed - no work required.
ITCP-2020-08	Lack of bus stop	Turn into Egleton village from the A6003	Egleton	09/03/2020	Closed - no work required.
ITCP-2022-08	30mph speed limit requested	Church Road	Egleton	01/03/2022	Initial Assessment
ITCP-2022-09	30mph speed limit requested	Hambleton Road	Egleton	01/03/2022	Initial Assessment
ITCP-2020-22	Speed of vehicles combined with shared road usage - concern for safety.	Egleton turn to Manton	Egleton and Gunthorpe	20/07/2020	Closed - strategic scheme to be considered under Local Cycling and Walking Infrastructure Plan
ITCP/2017/04	Safety concerns	The cross roads on Grantham Lane,	Empingham	19/07/2017	No work required
ITCP/2018/07	Lack of crossing point	A606	Empingham	29/04/2016	No work required
ITCP/2019/03	Safety of children travelling to school	Main Street and Willoughby Drive	Empingham	07/03/2019	Completed
ITCP-2019-19	Collision cluster site	A606 - Normanton Park Road junction	Empingham	22/09/2019	Completed
ITCP-2019-45	Speeding Traffic and pedestrian safety	40mph buffer zones on the A606	Empingham	28/11/2019	Completed
ITCP-2019-45b	Further feasibility to address pc comments.	Stamford Road	Empingham		Completed

ITCP-2020-15	Speeding traffic and pedestrian safety	40mph buffer zones on the A606 - Stamford entrance	Empingham	28/11/2019	Merged or removed
ITCP-2020-52	Skid resistance	C1008 Horn Lane (site 2432)	Empingham	12/10/2020	Merged or removed
ITCP-2020-58	Skid resistance	C1013 Grantham Lane (sites 4864/6251/2747)	Empingham	12/10/2020	Merged or removed
ITCP-2020-74	Cycleway footway provision	Stamford towards Empingham (via Stamford Road).	Empingham	07/08/2020	In feasibility
ITCP-2021-57	Speeding	Highfields Close/ Exton Road	Empingham	18/11/2021	Closed - No works required
ITCP-2019-15	Road safety	A6121 - both entrances to village and junction with Plover Road	Essendine	02/07/2019	Completed
ITCP/2016/18	Safety concerns	Coach Road	Exton	22/09/2014	No work required
ITCP-2020-25	Speeding	Garden Road, Empingham and Stamford Road	Exton	04/09/2020	Closed - No works required
ITCP-2020-47	Skid resistance	C1019 Cottesmore Road (site 1700)	Exton	12/10/2020	Merged or removed
ITCP-2021-58	KSI site	Barnsdale Avenue, Exton, Rutland	Exton	22/11/2021	No Works required
ITCP-2022-35	Parked Cars	The Green	Exton	19/12/2022	Initial assessment
ITCP-2022-36	Speeding	A606	Exton	19/12/2022	Closed - No works required
ITCP/2019/01	Speeding on bend of road	Bend on Barnsdale Avenue/ Cottesmore Road - at the junction with Oakham Road.	Exton and Horn	10/01/2019	Completed
ITCP/2017/07	Speeding	A47	Glaston	26/09/2017	No work required
ITCP-2020-62	KSI site	Wing Road	Glaston	09/01/2020	No work required
ITCP/2018/11	Speed Limit Review, road width and congestion.	Pickworth Road and Water Lane	Great Casterton	28/11/2018 and 22/11/2018	No work required

ITCP-2020-33	KSI site	B1081 junction with A1 south bound slip road	Great Casterton		No work required
ITCP-2021-31	KSI site	Ryhall Rd, Grt Casterton	Great Casterton	09/08/2021	No works required
ITCP-2021-52	Existing traffic calming measures looking worn	Chicanes at North and South ends of Main Street (Old Great North Road)	Great Casterton	11/11/2021	No Works required
ITCP-2022-02	Existing traffic calming measures looking worn	Old Great North Road, Great Casterton	Great Casterton	19/01/2022	Closed - duplicated enquiry
ITCP-2022-07	Extension to 30mph zone	Little Casterton Road	Great Casterton	09/02/2022	Closed - No works required
ITCP/2017/02	Narrow pavement	Junction of Main Street and Pond Lane	Greetham	31/01/2017	Completed
ITCP-2020-04	Speeding traffic and pedestrian safety	Church Lane and corner Main Street (West End side)	Greetham	27/01/2020	Closed - no work required.
ITCP-2020-05	Safety concerns over chicane priority sign	Main Street outside village shop/village green	Greetham	27/01/2020	Completed
ITCP-2020-39	Skid resistance	B668 Stretton Road (site 565)	Greetham	12/10/2020	Merged or removed
ITCP-2021-26	KSI	Hooby Lane	Greetham	09/07/2021	No works required
ITCP-2021-42	Vehicles travelling too fast	Main Street and Stretton Rd Greetham	Greetham	10/09/2021	Closed - No works required
ITCP-2021-48	Request for two pedestrian crossings in village	Northbrook Close / Locks Close and near 66 Main Street	Greetham	19/10/2021	Initial Assessment
ITCP-2021-51	Parking - loading vehicles causing an obstruction	Pond Lane, Greetham. Opposite side entrance to Oak House Residential Home	Greetham	08/11/2021	No work required
ITCP-2022-29	KSI 15/6/2022	B668 Stretton Road, Greetham	Greetham	10/11/2022	Closed - No works required
ITCP-2022-32	Request for speeding enforcement	Greetham	Greetham	16/11/2022	Awaiting initial assessment

ITCP/2017/11	Lack of footway/ cycleway - concern for safety and isolation.	Wood Lane crossroad to Stretton	Greetham and Stretton	16/11/2017	Closed - strategic scheme to be considered under Local Cycling and Walking Infrastructure Plan
ITCP-2023-04	Road Safety	A6003 Through Gunthorpe	Gunthorpe	14/02/2023	Initial Assessment
ITCP-2021-13	Parked cars blocking Fire Engine access	Lyndon Rd,(South end) Hambleton Peninsular	Hambleton	09/04/2021	On hold
ITCP/2016/08	Uneven pavement	High Street	Ketton	03/11/2016	Completed
ITCP/2018/01	Safety concerns for cyclists and pedestrians	Northern footway on the A6121, Ketton - approximately between Chater Lodge and The Gate Lodge.	Ketton	04/04/2018	Progress or construct
ITCP/2018/04	Traffic management and civil enforcement review	Church Road and Empingham Road	Ketton	22/08/2019	Completed
ITCP/2018/05	Road safety concerns	Barrowden Road & the junction of Barrowden Road/Geeston Road	Ketton	04/10/2018	Completed
ITCP/2019/02	Plant growth narrowing road.	Bend on Station Road	Ketton	07/02/2019	No work required
ITCP-2019-27	Traffic: Vehicles are travelling too fast; Not enough time to cross the road; The road is being used as a rat run; There is no safe place to cross the road; Traffic is queueing at peak times.	Junction of High Street and Pit Lane	Ketton	28/07/2019	No work required
ITCP-2020-06	Road Safety - request for footway LHS of carriageway	Geeston settlement carriageway	Ketton	12/02/2020	Progress or construct

ITCP-2020-29	Speeding and overtaking	Luffenham Road, Stamford Road and Empingham Road	Ketton	01/10/2020	Closed - No works required
ITCP-2021-05	Inconsiderate parking	Various locations within Aldgate	Ketton	19/01/2021	On Hold
ITCP-2021-12	Speeding	A6121 on the south-western outskirts of village	Ketton	16/03/2021	Initial Assessment
ITCP-2022-34	Road markings	Park View Estate	Ketton	25/11/2022	Closed - No works required
ITCP-2020-73	Cycleway footway provision	Enhancements to existing cycleway footway on the A6121, Ketton - approximately between Chater Lodge and The Gate Lodge. Plus Tinwell to Stamford	Ketton and Tinwell	07/08/2020	In feasibility
ITCP/2016/07	Accident cluster site	Junction of Burley Road and Oakham Road	Langham	30/06/2017	No work required
ITCP/2017/12	Concerns regarding safety and isolation due to traffic volume and speed	A606	Langham	14/11/2017	No work required
ITCP-2019-37	Parked vehicles are causing an obstruction	Burley Road, from Langham CofE Primary school to Ashwell Road	Langham	02/10/2019	No work required
ITCP-2020-27	Pedestrian safety	A606, Main Road	Langham	07/09/2020	No Works required
ITCP-2022-03	Lack of parking	Allotment and play park on Burley Road	Langham	20/01/2022	On Hold
ITCP-2021-40	Accident site	Bend and hilltop on road from Langham to Whissendine	Langham / Whissendine	09/09/2021	Completed

ITCP/2017/01	Lack of footpath	Main Road	Little Casterton	19/01/2017	Closed - no work required.
ITCP/2017/08	Speeding	Eastern entrance to village	Little Casterton	12/10/2017	Completed
ITCP-2019-31	Speeding traffic	Road between Toll Bar towards Little Casterton	Little Casterton		Completed
ITCP-2020-68	KSI site	C9304 Ryhall Road on bend near Salters Lane	Little Casterton	13/08/2020	No work required
ITCP-2023-03	Road Safety	Little Casterton Village	Little Casterton	07/02/2023	Initial assessment
ITCP-2019-23	Speeding and safety	Main Street	Lyddington	10/07/2019	Completed
ITCP-2022-21	KSI	Main Street Lyddington	Lyddington	02/06/2022	Closed - No works required
ITCP/2017/13	Lack of dedicated cycle route	Lyndon Top	Manton	2016	Progress or construct
ITCP-2020-16	Lack of cycle way through village	Manton village to existing cycleway near Chater Road	Manton		Closed - strategic scheme to be considered under Local Cycling and Walking Infrastructure Plan
ITCP-2020-34	KSI site	A6003 north of Manton	Manton		Completed
ITCP-2020-70	KSI site	A6003 - bridge between Manton and Preston	Manton	19/08/2020	Completed
ITCP-2020-76	Speed and volume of traffic including HGVs	Lyndon Road and Wing Road	Manton	24/11/2020	Closed - No works required
ITCP-2022-25	Cycleway footway provision (ITCP/2017/13)	Lyndon Top	Manton	12/09/2022	Initial assessment
ITCP-2022-26	Roundabout layout and lack of signage	Chater Close/ Lyndon Road	Manton	12/09/2022	Awaiting initial assessment
ITCP/2019/08	Speeding, use of road as cut through and lack of pavement	Bowling Green Lane	Market Overton	01/05/2019	Completed
ITCP-2021-27	Dangerous camber	Footpath E108	Market Overton	13/07/2021	Awaiting initial assessment

ITCP-2021-62	Collapsed Bridge	E105 South West of Market Overton	Market Overton	19/10/2021	Completed
ITCP-2019-26	Vehicles putting cyclists in danger	Thistleton Road, between Market Overton and Thistleton	Market Overton and Thistleton	26/07/2019	Closed - strategic scheme to be considered under Local Cycling and Walking Infrastructure Plan
ITCP/2019/05	Speeding	Junction of A47 and A6121	Morcott	03/03/2019	No work required
ITCP-2020-21	Lack of footway - concern for safety	Short section of B672 to footway along A47.	Morcott	26/06/2020	Closed - no work required.
ITCP-2021-25	PROW Bridge Stability	End of Pringle Lane	Morcott	25/06/2021	Completed
ITCP-2021-50	Speed Limit Review	20mph areas within village	Morcott	29/10/2021	Feasibility and design
ITCP-2021-61	KSI	A47 GLASTON ROAD MORCOTT JW ROAD TO MORCOTT VILLAGE.	Morcott	10/01/2022 Accident October 2021	No works required
ITCP-2020-48	Skid resistance	C1010 Wytchley Warren Lane (site 1900)	Normanton	12/10/2020	Merged or removed
ITCP/2018/09	Lack of pedestrian route	Edith Weston Road	North Luffenham	01/01/2016	No work required
ITCP-2019-35	Parking	Lyndon Road	North Luffenham	03/09/2019	No work required
ITCP-2021-15	Speeding	Edith Weston Road	North Luffenham	20/04/2021	Initial assessment
ITCP-2022-28	Speed survey request	Edith Weston Road - The Oval	North Luffenham	10/11/2022	Duplicated enquiry - see ITCP-2021-15
ITCP/2016/01	Safety of pavement	Jules House, Cold Overton Road	Oakham	23/10/2014	No work required
ITCP/2019/11	Speeding	Braunston Road	Oakham	29/05/2019	Completed
ITCP/2019/12	Road safety	Lands' End Way (VAR Center)	Oakham	25/05/2019	No work required
ITCP-2019-17	Collision cluster site	A606, Burley Park Way junction with Kestrel Road	Oakham	Accident Cluster Site	No work required
ITCP-2019-21	Collision cluster site	High Street/ Burley Road junction	Oakham	Accident Cluster Site	No work required
ITCP-2019-22	Collision cluster site	Park Lane/ Barleythorpe Road junction	Oakham	Accident Cluster Site	No work required

ITCP-2019-28	Speeding and safety concerns relating to junction of Farriers Reach.	Lands' End Way/ Farriers Reach	Oakham	16/07/2019	Completed
ITCP-2019-34	Disabled parking bay	Derwent Drive	Oakham	20/08/2019	Merged or removed
ITCP-2019-36	Parked vehicles causing obstruction	Huntsman Drive	Oakham	13/09/2019	On hold
ITCP-2019-38	Vehicles putting cyclists in danger	Braunston Road - Between roundabout and hill as you leave Oakham towards Braunston	Oakham	02/10/2019	Merged or removed
ITCP-2020-11	Road safety - speeding vehicles within school 20mph zone.	Burley Road outside of Oakham C of E	Oakham	17/03/2020	Closed - No works required
ITCP-2020-12	Parked vehicles causing obstruction	Willow Crescent	Oakham	17/03/2020	No works required
ITCP-2020-18	Parked cars causing obstruction and speeding traffic	Princess Avenue	Oakham	22/04/2020	No work required
ITCP-2020-23	Road safety	Spinney Hill	Oakham	17/08/2020	Merged or removed
ITCP-2020-31	Speeding	Bypass, near Alsthorpe Road junction	Oakham	16/10/2020	Closed - No works required
ITCP-2020-41	Skid resistance	B640 High Street (site 2952)	Oakham	12/10/2020	Merged or removed
ITCP-2020-42	Skid resistance	B640 High Street (sites 2982/2457/3288)	Oakham	12/10/2020	Merged or removed
ITCP-2020-51	Skid resistance	C1004 Cold Overton Road (site 2285/2418)	Oakham	12/10/2020	Merged or removed
ITCP-2020-54	Skid resistance	C1005 Braunston Road (site 3250)	Oakham	12/10/2020	Merged or removed
ITCP-2020-64	KSI site	C5305 High Street	Oakham	09/02/2020	No work required
ITCP-2020-66	KSI site	Braunston Road	Oakham	17/07/2020	No work required

ITCP-2020-72	Cycleway footway provision	Burley Road	Oakham	07/08/2020	Completed
ITCP-2021-11	Speeding trafficking	Princess Avenue and surrounding roads	Oakham	01/01/2021	Closed - No works required
ITCP-2021-17	Lack of parking/ traffic flow	Burley Road	Oakham	17/05/2021	Closed - no work required.
ITCP-2021-29	Parking Issues	King Road, Oakham	Oakham	21/07/2021	Merged or removed
ITCP-2022-16	Bus Layby & Shelter	Uppingham Road, Oakham	Oakham	01/06/2022	Awaiting initial assessment
ITCP-2022-17	2.5 Section of cycleway	Uppingham Road, Oakham	Oakham	01/06/2022	Awaiting initial assessment
ITCP-2022-18	Lack of dropped Crossings	Edmonton Way Estate, Oakham	Oakham	31/05/2022	Feasibility and design
ITCP-2020-09	Pedestrian safety - lack of connecting footways	Ashwell Road (from the roundabout and the Veterinary surgery)	Oakham	17/03/2020	Closed - strategic scheme to be considered under Local Cycling and Walking Infrastructure Plan
ITCP-2020-10	Parked vehicles causing obstruction	Kings Road	Oakham	17/03/2020	No work required
ITCP-2020-13	Road safety - speeding vehicles and signage concerns	Mount Pleasant on Uppingham Road	Oakham	19/03/2020	Closed - no work required.
ITCP-2021-03	Speeding vehicles (including cyclists)	Village entrance - approaching from Holywell	Pickworth	08/02/2021	Closed - No works required
ITCP-2020-36	Skid resistance	A6003 Oakham Road (sites: 4610/5790)	Preston	12/10/2020	Merged or removed
ITCP-2020-56	Skid resistance	C1012 Wing Road (site 3482)	Preston	12/10/2020	Merged or removed
ITCP-2021-07	Safety concern	Bus shelter on A6003	Preston	18/02/2021	In feasibility
ITCP-2021-21	Speeding / safer footpath between villages	Belmesthorpe Road,	Rhyall	04/06/2021	Merged or removed

ITCP-2022-15	Speeding	Back Road	Ryhall	27/05/2022	Closed - No works required
ITCP/2017/10	Speeding	St Ebbas Close	Ryhall	15/11/2017	Completed
ITCP/2018/13	Volume of traffic and lack of pedestrian crossing point, speed of vehicles, bus pull ins	Various sites	Ryhall	19/12/2018	Completed
ITCP-2019-32	Speeding traffic	Village entrances on A6121 from Bourne and Stamford	Ryhall	20/08/2019	Completed
ITCP-2020-35	Skid resistance	A6121 Turnpike Road (site 2271)	Ryhall	12/10/2020	Merged or removed
ITCP-2020-37	Skid resistance	A6121 Stamford Road (sites: 5157/2692)	Ryhall	12/10/2020	Merged or removed
ITCP-2020-38	Skid resistance	A6121 Turnpike Road (site 5303)	Ryhall	12/10/2020	Merged or removed
ITCP-2020-63	KSI site	C9304 Ryhall Road	Ryhall	15/01/2020	No work required
ITCP-2021-16	Safety of pedestrians/ cyclists	Belmesthorpe Lane	Ryhall	05/05/2021	Closed - no work required.
ITCP-2021-22	Road surface dressing and traffic calming	Rutland Way, Church Street, The Square and New Road Ryhall	Ryhall	10/06/2021	Closed - no work required.
ITCP-2019-18	Collision cluster site	A6121 Between Ryhall and Essendine	Ryhall and Essendine	Accident Cluster Site	Completed
ITCP-2020-01	Speeding vehicles	Particularly but not confined to west end of Main Street	Seaton	10/01/2020	No Works required
ITCP-2021-19	Speeding traffic and assessment for traffic calming measures	: Entry to Seaton village from Uppingham where Main Street becomes narrow and bends.	Seaton	26/05/2021	Merged or removed
ITCP/2016/02	Speeding	South Luffenham entrance	South Luffenham	31/05/2016	Completed
ITCP/2016/13	Speeding	A6121	South Luffenham	26/11/2016	Completed

ITCP/2016/14	Lack of pedestrian crossing	A6121	South Luffenham	29/11/2016	No work required
ITCP/2016/15	HGVs turning	Junction of A47 with Wireless Hill	South Luffenham	07/06/2016	No work required
ITCP/2016/16	Lack of pull in	Pinfold Lane	South Luffenham	31/05/2016	Completed
ITCP/2018/10	Accident cluster site	Wireless Hill roundabout	South Luffenham	-	Completed
ITCP/2019/06	Speeding, pedestrian safety and bus stop access	A6121	South Luffenham	14/04/2019	completed
ITCP-2019-20	Collision cluster site	Wireless Hill	South Luffenham	Accident Cluster Site	No work required
ITCP-2020-46	Skid resistance	C1018 Station Road (site 1218)	South Luffenham	12/10/2020	Merged or removed
ITCP-2020-57	Skid resistance	C1018 Wireless Hill (site 4068)	South Luffenham	12/10/2020	Merged or removed
ITCP-2020-69	KSI site	A6121 Stamford Road, 400m north east of Station Road	South Luffenham	18/08/2020	No works required
ITCP-2021-54	Speed Limit Review	20mph areas within village	South Luffenham	17/11/2021	Feasibility and design
ITCP-2022-04	KSI Site	A6121 SOUTH LUFFENHAM ROUNDABOUT WITH STATION ROAD	South Luffenham	03/02/2022	No Works required
ITCP/2019/07	Speeding	Manor Road, Stocken Hall Road and Clipsham Road	Stretton	15/04/2019	Completed
ITCP-2020-78	KSI site	B668 Greetham Road, junction with Wood Lane	Stretton	27/08/2020	Closed - no work required.
ITCP-2022-01	Narrow pavement. Speeding.	Clipsham Road	Stretton	17/01/2022	Initial Assessment
ITCP-2022-23	KSI	A1 NB at on-slip with A606 Empingham Road, Stamford, Leics	Stretton	27/08/2022	Closed - No works required
ITCP-2022-24	KSI	A1 Northbound prior to slip to B668	Stretton	06/09/2022	Closed - No works required

ITCP-2019-30	Speeding traffic	Teigh Road, Road from Ashwell to Edmonthorpe. From the corner where there is a turn to Market Overton, past the 3 entrances to the village	Teigh	15/08/2019	Closed - no work required.
ITCP-2021-24	KSI site	Teigh Rd, Ashwell	Teigh	03/06/2021	No works required
ITCP/2017/06	Speeding	Junction with Fosse Lane, Thistleton Road and Main Street at the eastern end of the village from Witham Road.	Thistleton	04/09/2017	Completed
ITCP-2021-37	Vehicles are travelling too fast;Not enough time to cross the road;There is no safe place to cross the road	Main St	Thistleton	18/08/2021	Completed
ITCP-2020-32	Road safety	Thorpe by Water - bend (X : 490122 Y: 297128)	Thorpe by Water	21/10/2020	Initial assessment
ITCP-2020-43	Skid resistance	B672 New Road (site 6402)	Thorpe by Water	12/10/2020	Merged or removed
ITCP/2016/05	Accident cluster site	B1081, Old Great North Road	Tickencote	30/06/2017	Completed
ITCP/2016/09	HGVs turning	Mill Lane	Tinwell	27/12/2015	Completed
ITCP/2018/03	Speeding vehicles causing concern for safety	the A6121 (Main Street) and Casterton Lane	Tinwell	20/07/2018	Completed

ITCP/2019/10	Speeding and overtaking	A47 between Barrowden and Duddington - particularly in the area of the two junctions into Tixover village to the south and the road to Tixover Grange to the north.	Tixover	10/05/2019	Completed
ITCP/2016/03	Speeding	Springback Way, Uppingham	Uppingham	01/12/2013	Completed
ITCP/2018/08	Concern regarding the roundabout	Seaton Road	Uppingham	08/04/2014	No work required
ITCP/2019/04	Access for children using public transport	Bus Drop off outside Uppingham C of E primary school	Uppingham	10/03/2019	Completed
ITCP-2019-14	Parking	Stockerston Rd, from the School Theatre westwards	Uppingham	11/06/2019	On hold
ITCP-2019-41	Junction alignment at Reeves Yard	Junction of Queens Street, Reeves Yard and South View	Uppingham	18/10/2019	Closed - no work required.
ITCP-2019-43	Safety and capacity issues at Uppingham bus interchange.	North Street East	Uppingham	09/09/2019	Closed - no work required.
ITCP-2020-30	Skid resistance	A47 Leicester Road (Site 774, 850 & 5721)	Uppingham	12/10/2020	Merged or removed
ITCP-2020-40	Skid resistance	B664 North Street West (site 2892)	Uppingham	12/10/2020	Merged or removed
ITCP-2020-67	KSI site	B664 North Street West, junction with Stockerston Road	Uppingham	18/07/2020	No work required
ITCP-2020-71	Cycleway footway provision	Ayston Road	Uppingham	07/08/2020	In feasibility
ITCP-2021-01	Narrow footway	outside Exeter Arms, Leicester Road	Uppingham	22/01/2021	No Works required

ITCP-2021-20	Lack of dropped kerb	B664	Uppingham	21/05/2021	Completed
ITCP-2021-36	Concern that crossing is abused by people / vehicles	LE15 9QJ The crossroads at the junction of Orange St, Ayston Rd, and North Street East and West	Uppingham	18/08/2021	No works required
ITCP-2021-49	KSI site	C8407 GLASTON ROAD UPPINGHAM AT ENTRANCE TO GARDEN CENTRE	Uppingham		No Works required
ITCP-2021-53	KSI Site	Wheatley Av, Uppingham	Uppingham	15/11/2021	No works required
ITCP-2022-22	Noise associated with traffic and speeding	A6003/ London Road - Spring Back Way to Uppingham community college	Uppingham	12/07/2022	Awaiting initial assessment
ITCP-2022-27	Request for yellow lining	Norton Street	Uppingham	05/10/2022	Awaiting initial assessment
ITCP-2021-56	Concern regarding accidents / road surface	A6003 The location is 1.3 miles from the end of Uppingham 30mph speed limit and 1.8 miles from the Caldecott 40mph sign on the A6003	Uppingham and Caldecott	17/11/2021	No works required
ITCP-2022-20	Signage Issue	A47 Wardley turn	Wardley	18/06/2022	Feasibility and design
ITCP/2017/03	Narrow lane with no 'pull ins'	Cow Lane	Whissendine	19/07/2017	Completed
ITCP-2019-44	Parking and perceived safety issues	Main Street incl Oakham Road and Stapleford Rd junctions, Ashwell Road inc Station Road junction, Cow Lane and the green.	Whissendine	10/11/2019	On hold
ITCP-2020-61	Skid resistance	C1002 Ashwell Road (site 6142)	Whissendine	12/10/2020	Merged or removed
ITCP-2022-12	Road signage to warn of flooding	Whissendine main St, Cow Lane, The Nook	Whissendine	14/03/2022	Progress or construct

ITCP/2016/04	Accident cluster site	A606/ Barnsdale Avenue junction	Whitwell	30/06/2017	No work required
ITCP-2020-20	Speed of vehicles causing a safety concern	Wing Hill, Top Street and Morcott Road	Wing	22/05/2020	Closed - No works required